

Roll with us on Social Media!



LEARN MORE
ABOUT MYTE



LIMITED WARRANTY (1 YEAR)

Covers defects that may be present, such as electrical components.

Please do not return to the store for any warranty issue. Visit www.Randy's.com/warranty for any issues.



Randy's MYTE

510 THREAD BATTERY



INSTRUCTION MANUAL

SPECIFICATIONS

Battery Capacity: 500mAH

Current: 3A

Output Voltage: 1.8-4.2V

Charging Port: USB-C charger (5V/0.5A).

Charge Time: About 60 minutes.

Resistance: $\geq 0.8\Omega$

POWER ON/OFF

Quickly press the Power Button 5 times within 1.5 seconds. The screen will turn off after 10 seconds of inactivity.

CHARGING

While charging, the display shows the battery level. The device is fully charged when all 4 icons are lit.

Device can NOT be used while charging.

POWER INDICATOR

Press the power button once to check the battery level (shown by 4 icons).

When the battery is below 10% or the voltage drops under 3.2V, the last icon will flash.

PREHEATING

Activate: Press the Power Button 2 times quickly. The device will preheat for 8 seconds at 1.8V.

Stop: Press any button.

ADJUST VOLTAGE

Press: the power button 3 times quickly to enter voltage mode.

Use: the up or down switch to change the voltage in 0.1V steps (range: 1.8V-4.2V).

Hold the switch to adjust faster.

Exit: If no buttons are pressed for 3 seconds, the device will exit voltage mode.

Default Setting: 2.8V.

IMPORTANT INFO

Vaping Timeout: If vaping exceeds 10 seconds, the screen will flash and the device will enter standby mode.

Short Circuit Protection/Resistance

Overload: Full screen will flash 4 times and enter standby mode.

No Cartridge Detected: Full screen will flash 3 times and enter standby mode.

SCREEN SETTINGS

Switch Screens: Press button 3 times to switch the screen display.

Turn Off Light Display: Press button 4 times to turn display lights off and on.